## MINUTES FOR PROJECT ENGINEERS MEETING

## Tuesday, June 25, 2002 2:15 p.m. Conference Room 'C'

1	CADD & PC Update
2.	Safety Issues
3.	FHWA Plan ReviewRicky Keith
	We are getting some comments back that probably relate more to our office policy than to actual errors or questionable design issues. Please respond in a courteous manner and refer to our policy or the Design Manual. This type of comment should begin to decrease as more plans are reviewed. Let me know how this is going in the future.
4.	Preliminary Plan Review
5.	Dead Files

## 6. Other

- Tie Rods on prestressed girder diaphragms be sure to recess and grout <u>all</u> ends of tie rods on skewed structures in highly corrosive environments and not just the two outside ones.
- If we need to do top down construction for permit issues a note should be shown on the plans. Tom will develop a standard note for this.
- Keep your calendars up-to-date and please respond to meetings scheduled as to whether or not you will attend. Send a representative if you cannot.

- Job postings we are now posting more positions. Please interview and try to find people to fill these.
- Buffer Rule Bridges Are we having problems with project schedules? Keep us informed on any problems getting information to get your work done.
- End Slopes Hydro Reports should now be showing 1½:1 unless we have something unusual. If you see 2:1 you should question this. If Soils needs 2:1 later we can adjust.